Preliminary Assessment Review Form

Site Name: Magnus Chemical Company

Aliases:

Address: 608 South Ave. City: GARWOOD BARK County: UNION

State: NJ

Priority Rating Given:

(By State or Contractor)

Agree: Disagree: (Check One)

If Disagree, Why?

Site STATUS: Site Description: 5 underground strage tanks

Other Comments:

are in place on this sits but are not in ust. Here tanks may have contained some Logardons omaterials. There is a possibility that there

in turn could effect the rearest wells

Recommendation: Final (By EPA)

(w/in 3 miles) while draw the drunkable water

Reviewer: Date: